

# Changelog

## Table of Contents

1	Products affected.....	2
2	New firmware features .....	2
3	Issues fixed .....	2
4	Upgrade procedure.....	3

# 1 Products affected

Commercial reference	Product	FW version
LSS100100	Wiser for KNX	2.1.1
LSS100200	spaceLYnk	2.1.1

Table 1: Products affected

## 2 New firmware features

- PowerTag profile
- Modbus error log
  - Modbus errors are displayed in separate error log
- Modbus – profiles updated to 64bit (8byte signed int)
- KNX connection / mode renaming
  - EIBnet deleted from mode names
- Trend logs – aggregate function (each trend stores data for 3 periods)
  - Every minute (for the last hour)
  - Once every x minutes (x = selected by user)
  - Once per day
- Help page
  - Content has been deleted and replaced by copyright information
- Update of default Apps
  - Touch 20180724
  - FB Editor 2.0 – 20180709
- New languages
  - Hungarian
  - Polish
  - Swedish
- New translation of the controller and default apps in all available languages

## 3 Issues fixed

- Smartphone view – missing home, logout button have been added
- Modbus device profile – unable to download
- Print script listings – unable to open

## 4 Upgrade procedure

1. Click *Configurator* -> *System* -> *System* -> *Upgrade firmware*
2. Find firmware for your product
3. Click **OK**

**Note:** It is highly recommended to create backup of your actual project before upgrade!

**Note:** We recommend to use always the latest firmware because of optimalization of writing data to microSD cards, running services, cyber security etc.

**Note:** Check HW version of your logic controller. There are available HW 1.xx, HW 2.xx and HW 3.xx in parallel on the market. HW version is located in the side label of the controller.